

General Environmental Incident Summary

Incident: 4126 **Date/Time Notice:** 6/9/2016 **DEM Incident No:**
Responsible Party: DLC
Date Incident: 6/9/2016 **Time Incident:** 1930 **Duration:** 1 minutes
County: Dunn **Twp:** 146 **Rng:** 96 **Sec:** 11 **Qtr:**
Lat: 47.48104 **Long:** -102.86560 **Method:** Navigation quality GPS
Location Description: Bear Creek NGL Pipeline Spread 1 Station 375+76

Submitted By: Chase Edmiston **Affiliation:**
Address: 100 West Fifth St
City: Tulsa **State:** OK **Zip:**

Received By:

Contact Person:

2729 Paintball Way
Bismarck, ND

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Frac Out

Description of Released Contaminant: Drilling Mud (Water and Bentonite)

Volume Spilled: 10.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Frac out caused during drilling activity

Risk Evaluation:

No immediate risk

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Localized area was affected and contained. No impacts to surface waters or other environmentally sensitive areas

Action Taken or Planned:

Drilling mud immediately stopped, contained with silt fence, and cleaned up

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 6/13/2016 ***Status:*** No Further Action Requested

Author: Souder, Taylor

Updated Volume:

Notes:

According to the report, the release of drilling mud came from pipeline installation. No further follow-up needed.